


1885088 O-Linden Side Table

Parts and Hardware List


A.	Top Assembly	1 pc
B.	Stationary Shelf	1 pc
C.	Legs	4 pcs
D.	Metal Brackets	4 pcs
E.	Phillips Head Screws	12 pcs
F.	Allen Head Bolts	4 pcs
G.	Lock Washers	4 pcs
H.	Flat Washers	4 pcs
I.	Allen Head Wrench	1 pc
J.	Phillips Head Screwdriver	1 pc

- * Please make sure that you have all the parts and hardware indicated above before you begin assembly of this item.
- * This item should be assembled on a soft surface to prevent scratching the finish during assembly.
- * This item may require periodic tightening.


Hardware Illustrations




E. Phillips Head Screw



F. Allen Head Bolt



G. Lock Washer



H. Flat Washer


Page 1 of 2 R1-10-20-04



1885088 O-Linden Side Table

Assembly Instructions

- 1. <u>Attach Metal Brackets (D)</u> Align the two pre-drilled holes in the Metal Brackets (D) with the two pre-drilled holes in the Legs (C). Secure with Phillips Head Screws (E) using Phillips Head Screwdriver (J). See illustration #1.
- 2. <u>Attach Legs (C)</u> Place the Top Assembly (A) upside down on a soft surface. Align the pre-drilled holes in the Legs (C) with the pre-threaded holes in the apron of Top Assembly (A). Secure with Allen Head Bolts (F), Lock Washers (G) and Flat Washers (H) using Allen Head Wrench (I). See illustration #1.
- 3. <u>Attach Stationary Shelf (B)</u> Put the item upright. Insert the Stationary Shelf (B) among the Legs (C) and align the pre-drilled holes in the bottom of Stationary Shelf (B) with the pre-drilled holes in the Metal Brackets (D). Secure with Phillips Head Screws (E) using Phillips Head Screwdriver (J). See illustration #2.



Page 2 of 2 R1-10-20-04